

# Background & Historical Issues



1900

Views towards the sailing club



1920's

Looking East towards the groyne

1930


Post Grantham Wall (concrete wave re-curve wall) construction



Groyne construction. Local cliff collapse visible

1954

Coastal Protection Report: River Hamble to Salterns Park



1960's

View towards the Sailing Club

1985

Osborne View



2005

Seawall failure at the 'kink' and repair

2012

Beach levels close to prom height



2014

2014: Gabion Basket Repairs following winter 2013/14 storms

2015

June: Hill Head Seawall Report - Recommendation to replace seawall



2016

Prom open but failed seawall remains

August: Beach levels fall damaging seawall foundations

December: Prom closure and seawall failure



Working together - protecting our coastline



**EASTERN SOLENT | COASTAL PARTNERSHIP**